# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY POLLUTION REPORT

TO

EPA Region 5 Records Ctr.

P.02

#### I. HEADING

Date: February 12, 1996

From: Cindy Nolan, OSC, U.S. EPA, Region V, EERB, RS-II

To: B. Watkins, OSWER, Washington, D.C.

R. Karl, Branch Chief, EERB, Chicago, IL

D. Bruce, Chief RS-II, EERB, Chicago, IL

B. Messenger, Chief ESS, Chicago, IL

J. Cisneros, Chicago Coordinator, Chicago, IL

J. Kujawa, ORC, CM-29A, Chicago, IL

T. Lesser, OPA, Chicago, IL

F. Lebensorger, IEPA, Maywood, IL

B. Everetts, IEPA, Springfield, IL

R. Roache, Department of Environmental Control, Maywood, IL.

Subject:

Mad

Harvey GRQ, Harvey, Cook County, Illinois.

POLREP#:

Thirteen (13)

#### II. BACKGROUND

Site ID No.: OV

Delivery Order No: 5001 05 655 Response Authority: CERCLA (ERB)

CERCLA Incident Category: Time-Critical Removal

CERCLIS ID #: ILD001128024

NPL Status: Non-NPL

Start Date: September 21, 1995

#### III. RESPONSE INFORMATION

## A. <u>Initial Situation:</u>

See initial POLREP.

## B. Actions Taken:

The following actions were accomplished during the period of February 5-9, 1996:

- 1. ERCS asbestos abatement subcontractor, Jet Vac, Inc. (JVI), continued to remove asbestos overhead piping insulation and asbestos-containing debris from the inside of the buildings.
- On 2-5, JVI conducted cleanup activities in Buildings E and I.
- 3. On 2-6, two rolloff boxes (46 yd³) of asbestos-containing material (ACM) and loose debris were disposed of at Community Landfill. Morris. Illinois. JVI conducted cleanup activities in Buildings E and I.

- 4. On 2-7, two rolloff boxes (56 yd³) of ACM and loose debris were disposed of at Community Landfill. JVI conducted cleanup activities in Buildings B and I.
- 5. On 2-8, two rolloff boxes (56 yd³) of ACM and loose debris were disposed of at Community Laudfill. JVI conducted cleanup removal activities in Buildings E and D.
- 6. On 2-9, one rolloff box (27 yd³) of ACM and loose debris was disposed of at Community Landfill. JVI conducted cleanup activities in Building D.
- 7. ERCS personnel air sampling was conducted. No elevated readings were found using PCM analysis

## IV. NEXT STEPS

- 1. Remove and dispose of all asbestos lying on the ground and from overhead piping inside of the buildings.
- 2. Organize disposal of drum and var contents.
- 3. Complete removing ACM in Buildings I and H and finish ground cleanup activities.

# V. KEY ISSUES

1. All tire removal activities have been completed. A final total of 4,055 tires were transported for recycling. IEPA funded the disposal of the tires to BFI Tire Recycling.

# VI. COSTS TO DATE as of 2/9/96

	AMOUNT BUDGETED	AMOUNT USED	AMOUNT REMAINING
US EPA	\$ 165,120	\$ 54,053	S 111,067
TAT*	\$ 28,000	\$ 24,321	S 3,679
START	\$ 25,000	\$ 9,204	\$ 15,796
ERCS	\$1,200,000	\$ 825,142	\$ 374,858
TOTAL	\$1,418,120	\$ 912,720	\$ 505,400

<sup>\* =</sup> TAT contract officially ended on 1-14-96.

## VII. DISPOSITION OF WASTES

Piping insulation removed to date	Loose ACM removed to date	Total ACM disposed to date
Outside: 4,648 L.F	Outside: 821 yd <sup>3</sup>	Outside: 1,094 yd <sup>3</sup>
Inside: 24,856 LF 1,660 ft <sup>2</sup> - 7SI on tanks 1,673 ft <sup>2</sup> - TSI on air ducts	Inside: 1,414 yd³	Inside: 2,104 yd <sup>3</sup>